

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Count
1	BRS	L1	3536	data same input same signal same vehicle	USPAT; EPO; JPO; DERWENT	2003/08/11 09:52		0
2	BRS	L2	2121	data same input same signal same vehicle same (control or controlling)	USPAT; EPO; JPO; DERWENT	2003/08/11 09:52		0
3	BRS	L3	0	data same input same signal same vehicle same (control or controlling) same coasting same storage	USPAT; EPO; JPO; DERWENT	2003/08/11 09:53		0
4	BRS	L4	0	data same input same signal same vehicle same coasting same storage	USPAT; EPO; JPO; DERWENT	2003/08/11 09:54		0
5	BRS	L5	0	vehicle same coasting same storage same time same switching-off	USPAT; EPO; JPO; DERWENT	2003/08/11 09:55		0
6	BRS	L6	8	vehicle same coasting same storage same time	USPAT; EPO; JPO; DERWENT	2003/08/11 09:59		0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
7	BRS	L7	3805	vehicle same location same (determined or determination)	USPAT; EPO; JPO; DERWENT	2003/08/11 09:59			0
8	BRS	L8	2	vehicle same location same (determined or determination) same coasting	USPAT; EPO; JPO; DERWENT	2003/08/11 10:00			0
9	BRS	L9	704	vehicle same control same coasting	USPAT; EPO; JPO; DERWENT	2003/08/11 10:01			0
10	BRS	L10	1	vehicle same control same coasting same switching-off same time	USPAT; EPO; JPO; DERWENT	2003/08/11 10:02			0
11	BRS	L11	171	vehicle same control same coasting same signal	USPAT; EPO; JPO; DERWENT	2003/08/11 10:03			0
12	BRS	L12	33	vehicle same control same coasting same input same signal	USPAT; EPO; JPO; DERWENT	2003/08/11 10:03			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
13	BRS	L1 3	53	vehicle same control same coasting same input same (signal or data)	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:25			0
14	BRS	L1 4	0	vehicle same control same coasting same input same (signal or data) same "switching off"	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:26			0
15	BRS	L1 5	3	vehicle same control same coasting same "switching off"	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:27			0
16	BRS	L1 6	15	method same "switching off" same vehicles	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:58			0
17	BRS	L1 7	265	701/19	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:59			0
18	BRS	L2 0	399	246/182B	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:59			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
19	BRS	L2 1	1315	180/170	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:59			0
20	BRS	L2 2	961	180/179	USPAT; EPO; JPO; DERWEN T	2003/08/11 10:59			0
21	BRS	L1 9	1149	246/182R	USPAT; EPO; JPO; DERWEN T	2003/08/11 11:24			0
22	BRS	L1 8	307	701/20	USPAT; EPO; JPO; DERWEN T	2003/08/11 11:54			0